

Oil Field Environmental Incident Summary

Incident: 20141019085223 **Date/Time of Notice:** 10/19/2014 08:52

Responsible Party: BOSQUE DISPOSAL SYSTEMS, LLC

Well Operator: BOSQUE DISPOSAL SYSTEMS, LLC

Well Name: JESSICA SWD 1

Field Name: BLUE BUTTES

Well File #: 90243

Date Incident: 10/18/2014 **Time Incident:** 17:30

Facility ID Number:

County: MCKENZIE

Twp: 150

Rng: 95

Sec: 23

Qtr:

Location Description:

Submitted By: Al, Hunt

Received By:

Contact Person: Al, Hunt
420 THROCKMORTON ST STE 640
FORT WORTH, TX 76102-3723

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	170	Barrels	170	barrels	170	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/16/2017

Clean Up Concluded: 11/4/2014

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

70 BBL spill was contained in temporary berm on east side of offload pad. 100 BBL spill was contained inside offload tank berm. VAC trucks were at facility 30 minutes after initial spill and salt water was put back into the system.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 10/24/2014 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak, remained on location within the diking according to the report. NDIC retains oversight.